

## ENGINEERING CHANGE NOTIFICATION FORM

ECN: 80200525	REV: 1	ISSUE DATE: 6/15/2015																
TYPE OF CHANGE: Firmware Modification																		
<b>DETAILED DESCRIPTION OF CHANGE:</b> Firmware release 0.73 for CSAC boards and 2.44 for FireFly-II related models includes improvements in handling leap second events and additional SCPI query commands that provide information on the pending leap second. For models with fixed position timing receivers, this firmware release also corrects an issue with obtaining a GPS fix if the unit is power-cycled while airborne.																		
<b>REASON FOR CHANGE:</b> Functionality improvements, added features and bug fixes.																		
<b>PRODUCTS AFFECTED:</b> <table border="1" data-bbox="131 730 1458 1213"> <thead> <tr> <th>Firmware Version</th> <th>Model</th> </tr> </thead> <tbody> <tr> <td rowspan="5"><b>Firmware 0.72 and previous versions for CSAC</b></td> <td>CSAC <sup>1</sup></td> </tr> <tr> <td>HD CSAC <sup>1</sup></td> </tr> <tr> <td>LN CSAC <sup>2</sup></td> </tr> <tr> <td>DROR-II <sup>2</sup></td> </tr> <tr> <td>DROR-IIA <sup>3</sup></td> </tr> <tr> <td rowspan="7"><b>Firmware 2.43 and previous versions for FireFly-II related products.</b></td> <td>FireFly-IIA</td> </tr> <tr> <td>FireFly-1C</td> </tr> <tr> <td>ULN-1100</td> </tr> <tr> <td>ULN-2550</td> </tr> <tr> <td>LC_1x1 Single Oven</td> </tr> <tr> <td>LC_1x1 Double Oven</td> </tr> <tr> <td>Mini-JLT</td> </tr> </tbody> </table>			Firmware Version	Model	<b>Firmware 0.72 and previous versions for CSAC</b>	CSAC <sup>1</sup>	HD CSAC <sup>1</sup>	LN CSAC <sup>2</sup>	DROR-II <sup>2</sup>	DROR-IIA <sup>3</sup>	<b>Firmware 2.43 and previous versions for FireFly-II related products.</b>	FireFly-IIA	FireFly-1C	ULN-1100	ULN-2550	LC_1x1 Single Oven	LC_1x1 Double Oven	Mini-JLT
Firmware Version	Model																	
<b>Firmware 0.72 and previous versions for CSAC</b>	CSAC <sup>1</sup>																	
	HD CSAC <sup>1</sup>																	
	LN CSAC <sup>2</sup>																	
	DROR-II <sup>2</sup>																	
	DROR-IIA <sup>3</sup>																	
<b>Firmware 2.43 and previous versions for FireFly-II related products.</b>	FireFly-IIA																	
	FireFly-1C																	
	ULN-1100																	
	ULN-2550																	
	LC_1x1 Single Oven																	
	LC_1x1 Double Oven																	
	Mini-JLT																	
<b>Notes:</b> <sup>1</sup> Requires CSAC GPSDO firmware variant <sup>2</sup> Requires LN CSAC firmware variant <sup>3</sup> Requires DROR-IIA firmware variant																		
<b>AVAILABILITY:</b> <table border="1" data-bbox="131 1356 1458 1423"> <thead> <tr> <th>MILESTONE</th> <th>DATE</th> </tr> </thead> <tbody> <tr> <td>ECN release for firmware release files</td> <td>6/15/2015</td> </tr> </tbody> </table>			MILESTONE	DATE	ECN release for firmware release files	6/15/2015												
MILESTONE	DATE																	
ECN release for firmware release files	6/15/2015																	
<p>Release 0.73 for CSAC based boards and 2.44 for FireFly-II related models provide the following improvements:</p> <p><b>Issue 1:</b></p> <p>For one second during an actual leap second event, the UTC time output has a 1 second error. This error is corrected in the following second when the unit has GPS reception.</p> <p><b>Resolution:</b></p> <p>Firmware 0.73 for CSAC and 2.44 for FireFly-II related models uses the pending leap second data provided by the GPS receiver to output the correct UTC time during a leap second event. GPS reception is required to initially obtain UTC time and the pending leap second data, but the unit outputs the correct UTC time during a leap second event even if GPS reception is lost.</p>																		

**Issue 2:**

Pending leap second information is not available to the user.

**Resolution:**

Firmware 0.73 for CSAC and 2.44 for FireFly-II related models adds the ptime:leap? query command that responds with the current leap second offset and pending leap second date and duration. The output is in the format

```
LEAPSECOND PENDING : 1
LEAPSECOND ACCUMULATED : 16
LEAPSECOND DATE : 2015,6,30
LEAPSECOND DURATION : 61
```

Individual parameters can also be queried separately with the ptime:leap:pending?, ptime:leap:accumulated?, ptime:leap:date? and ptime:leap:duration? commands.

**Issue 3:**

For models with fixed position timing receivers and when operating with airborne dynamics, the unit may fail to obtain a GPS fix after being power cycled. This issue only occurs with airborne dynamics and not with land- or sea-based dynamics.

**Resolution:**

Firmware 0.73 for CSAC and 2.44 for Mini-JLT corrects this issue on power-up allowing the unit to obtain a GPS fix while airborne.

**REFERENCE DOCUMENTS/ATTACHMENTS:**

CONTACTS	NAME	EMAIL
Software Engineer	Keith Loiselle	keith@jackson-labs.com

**PLEASE CONTACT JACKSON LABS TECHNOLOGIES, INC. WITH ANY QUESTIONS**