

ENGINEERING CHANGE NOTIFICATION FORM

ECN: 80200565 REV: 1 ISSUE DATE: 3/19/2018

TYPE OF CHANGE: Firmware Modification

DETAILED DESCRIPTION OF CHANGE:

Firmware release 3.05 for Mini-JLT GNSS for bug fixes and functionality improvements in uBlox receiver compatibility.

REASON FOR CHANGE:

Bug fixes and functionality improvements.

PRODUCTS AFFECTED:

Firmware Version	Model
Firmware 3.04 and previous	Mini-JLT GNSS

Notes:

AVAILABILITY:

MILESTONE	DATE
ECN release for firmware release files	3/19/2018

Release 3.05 for Mini-JLT GNSS provides the following improvements:

Issue 1:

The jamming level may frequently jump up to 100s due to modified power mode setup in the uBlox receiver with firmware version 3.01. Units with uBlox receiver of version 3.0 or older are not affected by this issue.

Resolution:

Firmware 3.05 corrects the issue by configuring the proper power mode setup to ensure low jamming susceptibility. This fix improves reliability related to the issue of preventing the device acquiring a lock due to consistent high jamming levels.

Issue 2:

The UTC date and time display from start-up is incorrect when GPS signal is not present.

Resolution:

Firmware 3.05 corrects the issue by starting the RTC counter from zero upon start-up before a GPS fix and UTC time is available.

REFERENCE DOCUMENTS/ATTACHMENTS:

CONTACTS	NAME	EMAIL
Software Engineer	Keith Loiselle	keith@jackson-labs.com

PLEASE CONTACT JACKSON LABS TECHNOLOGIES, INC. WITH ANY QUESTIONS