

ENGINEERING CHANGE NOTIFICATION FORM

ECN: 80200552	REV: 1	ISSUE DATE: 1/27/2017		
TYPE OF CHANGE: Firmware Modification				
DETAILED DESCRIPTION OF CHANGE:				
Firmware release 2.45 for FireFly-II related models includes bug fixes. This firmware addresses an issue only present in release 2.44.				
REASON FOR CHANGE:				
Bug fixes.				
PRODUCTS AFFECTED:				
Firmware Version		Model		
Firmware 2.44 versions for FireFly-II related	FireFly-IIA			
products.	FireFly-1C			
	ULN-1100			
	ULN-2550			
	LC_1x1 Single Ove	en		
	LC_1x1 Double Ov	en		
	Mini-JLT			
Notes:				

AVAILABILITY:

MILESTONE	DATE
ECN release for firmware release files	1/27/2017

Release 2.45 for FireFly-II related models provide the following improvements:

Issue 1:

When the unit is in forced holdover mode, the time of day fails to update. Forced holdover mode does not happen by itself, but is user-initiated with the SYNC:HOLDOVER:INIT command.

Resolution:

Firmware 2.45 for FireFly-II related models properly updates the time of day during forced holdover.

REFERENCE DOCUMENTS/ATTACHMENTS:		
CONTACTS	NAME	EMAIL
Software Engineer	Keith Loiselle	keith@jackson-labs.com

PLEASE CONTACT JACKSON LABS TECHNOLOGIES, INC. WITH ANY QUESTIONS

10191 West Park Run Drive, Suite 100, NV 89145 · USA · Phone: +1 (702) 233-1334 - Fax: +1 (702) 233-1073 · info@iackson-labs.com