

ECN #: 80200697 DATE: 11-APR-2022

REV #: 1.2

## **ENGINEERING CHANGE NOTIFICATION**

<b>CHANGE TYPE:</b>	FW Modification	<b>REASON FOR CHANGE:</b>	Bug fix
	Firmware release 3.17 includes functionality improvements and bug fixes to correct		
	auto-switching when SYNC:SOUR:MODE is set to AUTO.		

Products Affected			
Product Families	Models		
FireFly-IIA	FireFly-IIA-G2		
LC-1x1	LC-1x1-G2		
Mini-JLT	Mini-JLT-G2		
ULN-1100	ULN-1100-G2		
ULN-2550	ULN-2550-G2		

## **Detailed Change Notes:**

**Issue 1:** On firmware revision 3.16 or earlier of the above listed product families, 1PPS source would not switch automatically when SYNC:SOUR:MODE is set to AUTO.

**Resolution:** Firmware rev 3.17 is released to fix this issue. As of the release of this ECN, the above listed product families (except custom variants) will be shipped with firmware rev 3.17 or later.

Units in the field (with Firmware rev 3.16 or prior) that utilizes the AUTO 1PPS source feature will need to have the firmware updated to v3.17 or later.

## **Reference Documents / Attachments**

Firmware Update Instructions.pdf

TITLE	NAME	E-MAIL
Embedded Software Engineer	Min Lan	support@jackson-labs.com

## PLEASE CONTACT JACKSON LABS TECHNOLOGIES, INC. WITH ANY QUESTIONS