

ENGINEERING CHANGE NOTIFICATION FORM

ECN: 80200569A	REV: 1.2	ISSUE DATE: 6/14/2018
TYPE OF CHANCE.		

TYPE OF CHANGE:

Decision to populate J6 seondary 10MHz output connector on all Mini-JLT board versions.

DETAILED DESCRIPTION OF CHANGE:

Both BOMs rev1.6 90-19610 and 90-38917 will change row 27 from:

ROW # JLT PN DESCRIPTION MFG MFG PN QTY LOCATION 27 35-18276 SMA JACK EMERSON 142-0701-201 3 J2, J3, J4

TO:

27 35-18276 SMA JACK EMERSON 142-0701-201 **4** J2, J3, J4, **J6**

Adding J6 to all of Mini_JLT products. NEW BOMS will be Rev 1.7

NOTE: CUSTOM MINI-JLT VARIANTS ARE NOT AFFECTED.

REASON FOR CHANGE:

Customers wanted J6 on product variants

PRODUCTS AFFECTED:

DESCRIPTION	PRODUCT NUMBERS
Mini JLT boards	90-19610, 90-38917, 100291, 100292, 100293, 100294, 100295, 100297, 100303, 100307, 100308, 100310, and 100311.

AVAILABILITY:

MILESTONE	DATE
Units will be shipped with this ECN and BOM version updated as of	6/14/2018

IMPACT OF CHANGE & RECCOMENDED ACTION:

Effects factory board BOM and new assembly. No effect for units in the field.

REFERENCE DOCUMENTS/ATTACHMENTS:

CONTACTS	NAME	EMAIL
Product Manager	Said Jackson	support@jackson-labs.com

PLEASE CONTACT JACKSON LABS WITH QUESTIONS!